2/28/12

Hello Kenny,

Was able to boot system up O.K.
Ran QA on 32 and 20 channel head coils. Both passed twice.
Checked plugs and receptacles.
Ran spike check. No spikes found.
Ran protocol with artifacts on phantom with 32 channel coil.
Could not reproduce artifacts.
Will monitor over next couple of days.

Thanks,
Martin

Cable compartment

Spike noise